AMENDMENTS TO THE CLAIMS

This listing of claims will replace all prior versions, and listings, of claims in the application.

Listing of Claims:

1. (Currently Amended) A clothes dryer comprising:

a base forming a floor of a body;

a front cabinet forming a front portion of the body;

a side cabinet forming side portions of the body;

a back cover forming a back portion of the body;

a control panel having a hook; and

a top cover forming a top of the body wherein the top cover has a predetermined

curvature, and wherein the control panel is provided on a rear portion of the top cover, the top

cover comprising a groove provided at a rear portion of the top cover wherein the hook is

disposed in a surface of the control panel opposite the top cover such that the hook inserts into a

hole disposed in the groove; and

a fire-wall made of metal, and provided at a lower portion of the top cover.

2. (Previously Presented) The clothes dryer of claim 1, wherein the firewall has the

same predetermined curvature.

3. (Previously Presented) The clothes dryer of claim 1, wherein the groove is

provided along a rear side of the top cover and the groove has the same predetermined curvature.

2

Application No.: 10/663,997 Docket No.: 9988.058.00

Amdt. dated February 28, 2006

Reply to Office Action dated October 28, 2005

4. (Currently Amended) A laundry dryer comprising:

a body;

a top cover covering the body, the top cover including:

a groove which runs along a width of the top cover wherein the groove directs fluid on

the top cover toward an exterior of the laundry dryer;

at least one hole disposed in the groove; and

a control panel including a hook disposed at a surface of the control panel opposite the

top cover wherein the hook is configured for insertion into the at least one hole groove.

5. (Previously Presented) The laundry dryer of claim 4, wherein the top cover has a

curvature.

6. (Previously Presented) The laundry dryer of claim 5, further comprising:

a firewall disposed below the top cover, wherein the firewall has a curvature such that

fluid which leaks through the hole onto the firewall is directed to a lower portion of the body.

3